



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 6, 2011

Reviewed: PPW3

Mine Name: Pleasant	Permit Number: S/023/0109
Operator Name: Dale D. Rogers	Inspection Date: April 5, 2011
Inspector(s): Wayne Western	Time: 10:30 AM – 12: 10 PM
Other Participants: Dale Rogers	Mine Status: Proposed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Courtesy inspection, to meet with operator on site prior to the Division issuing permit.

Inspection Summary:

The Division still needs BLM concurrence before the permit can be issued.

There is some disturbance on site. The disturbance can be seen from Google Earth images.

The Division was unable to GPS the area due to technical difficulties.


Directions to the site:

From the south turn north from Highway 5/60 just before the Utah Nevada border. Travel north past Gandy and continue in Juab County. At the junction to Pleasant Valley turn west drive 7.7 miles and turn south and continue on till the mine with as the base of the foothills.

Conclusions and Recommendations:

The Division should inspect the site once approval has been granted.

Inspector's Signature



WHW:

cc: (OPERATOR)

Jerry_Mansfield@BLM.gov

O:\M023-Juab\S0230109- Pleasant\inspections\Insp-04052011.doc



Prior Disturbance looking west



Prior Disturbance looking west



Prior Disturbance and access road